

Instructions


No. 428BP

Installation / Instalación

Replaces American Standard No. 738651-0070A / Reemplaza al modelo No. 738651-0070A


1) Remove old seal

Quite sello viejo



2) Install new seal into groove

Instale nuevo sello en ranura



Flush Valve
Válvula de
descarga

Seal
Sello

